

Product Safety Recall

RECALL REF No:- IWR-PR-001.
DATE: 29th November, 2016
SUPPLIER NAME: Kuba Pty. Ltd T/A IWR Lifting
RECALL COVERAGE: State Wide
SOLD BETWEEN: June 2011 – 28th November 2016

PRODUCT DESCRIPTION: IWR BOW SHACKLES & PINS



Kuba Pty. Ltd T/A IWR Lifting as a responsible supplier is conducting a Recall of all *IWR Bow Shackles & Pins* with markings as shown above. The range of recall are rated at working limit (WLL 1.T to WLL 25T)

DEFECT - There is a concern that the shackle pin hardness value exceeds the requirements of Australian Standard AS2741-2002 and may be prone to fatigue crack initiation from stress raisers. This can potentially result in fatal injury and/or damage to the user or surrounding area.

WHAT TO DO - Customers are to cease using this product, remove from service and quarantine immediately. Customers may return this product to the original place of purchase to receive an equivalent compliant Bow Screw Pin Shackle replacement.

For further information, Customers may directly contact IWR Lifting on (02) 4274 4668 during normal working hours.

This recall advice is issued at the expense of;
Kuba Pty. Ltd T/A IWR Lifting (ABN 18 060 137 475)
12 Harris Street, Port Kembla. NSW. 2505

Bassanese, Bruno

From: Robinson, Justin
Sent: Friday, 2 December 2016 11:34 AM
To: Picks, Steven; Cairns, Nathan; Coleman, Steve; Carey2, Jeff; Wilcock, Doug; Bassanese, Bruno; Nicholls, Jay; Adams, Tony; Carey2, Jeff; Klynsoon, Tim; Allen, Scott
Cc: Kendrick, Clint; Andrew.Davidson@jhg.com.au; McLoughlin, Rick; Matt Hoffmann; James.O'Hara@decnil.com.au; Grant Richards (grant.richards@rcrtom.com.au)
Subject: FW: Bow shackle recall
Attachments: Safety Share 2016-12 Bow Shackle Pin Failure - External.jpg

Hello ALL

Effectively immediately can we ALL please undertake inspections of all 'bow-shackles' onsite on all our jobs.

- Dust 290
- MPOW
- 325km Bridge
- Abydoss Crossover
- TCB1 Demolition
- ZE TCB1

Of particular interest are the IWR-PR-001 Bow Shackles 1.0T – 25T as listed in the attached. Can we ensure the following shackles are put out of service and quarantined today and removed from site as soon as practicably possible.

NOTE - For any lifting that are currently underway please verify the rigging immediately and if required cease lifting and follow the process as listed above around the removal of these items from use.

Regards

From: Pollitt, Simon
Sent: Friday, 2 December 2016 9:46 AM
To: DL-IOR-WAIO-Lifting Coordinators <DL-IOR-WAIO-LiftingCoordinators@bhpbilliton.com>
Subject: Bow shackle recall

Hi all,

Not sure if you are all aware of this but there has been a recall on IWR shackles.

I have contacted our supplier and they do not supply this particular brand of shackle and it relates to shackles from the eastern states but worth being aware of in case you come across any.

Regards,

Simon Pollitt



Coordinator Lifting Services - Fixed Plant Maintenance – Jimblebar

BHP Billiton Iron Ore